

NABO NOW

See Page 15 for
NABO Grant
Information!

The Risks of Ammonia Refrigeration



Ammonia refrigeration is one of the oldest forms of refrigeration used for commercial and retail use. Ammonia has many advantages that make it a reliable refrigerant for most applications.

There are primarily two types: Dry and Flooded, both systems have advantages and disadvantages, the correct system for your application depends on use and cost.

Regardless of the application certain operating and safety standards are mandated for the protection of personnel that may suffer from exposure from leaks in ammonia systems. Proper safety equipment, alarms, and ventilation are important. Risks associated with Ammonia Gas “NH₃” are.

1. Respiratory and irritation to the eyes and skin.
2. Explosion risks
3. Contamination of water sources
4. Chemical burns
5. Neurological damage

State or Local Jurisdictions may have specific requirements that apply to the installation and operation of refrigeration systems.

The International Institute of Ammonia Refrigeration (IIAR) sets and develops standards following the American National Standards Institute (ANSI) procedures and is a ANSI accredited standards developer.

Ammonia Refrigeration PDF Compliance Guides can be obtained through OSHA.

Recall Notices

We do not claim to list all recall notices but highlight the ones we believe to be most pertinent to our members. To view all recalls, visit the Local, State, Federal, and Manufacturing websites.

Anker Power Banks Recalled Due to Fire and Burn Hazards; Manufactured by Anker Innovations

Hazard: The lithium-ion battery in the power bank can overheat, posing fire and burn hazards to consumers.

Remedy: Consumers should immediately stop using the recalled power banks and visit Anker’s Recall Page at <https://www.anker.com/rc2506> to verify the product serial number and register for the recall. Consumers with an impacted product should contact Anker Innovations Limited to receive a full cash refund, or an Anker gift card that can be used across a variety of Anker product lines. To receive the remedy, consumers will be required to submit a photo of their recalled power bank showing the model number, serial number, their name, the date of the photograph, and the word “recalled” written on the power bank in permanent marker. Anker will provide instructions for consumers on how to return or dispose of the recalled power banks.

Note: Do not throw this recalled lithium-ion battery or device in the trash, the general recycling stream (e.g., street-level or curbside recycling bins), or used battery recycling boxes found at various retail

and home improvement stores. Recalled lithium-ion batteries must be disposed of differently than other batteries, because they present a greater risk of fire.

Your municipal household hazardous waste (HHW) collection center may accept this recalled lithium-ion battery or device for disposal. Before taking your battery or device to a HHW collection center, contact that office ahead of time and ask whether it accepts recalled lithium-ion batteries. If it does not, contact your municipality for further guidance.

Units: About 481,000

Consumer Contact:


Website: <https://www.anker.com/rc2506>

E-mail: support@anker.com

Phone: [\(800\) 988-7973](tel:(800)988-7973)



Makita U.S.A., Inc. Recalls Cordless Grease Guns and Grease Gun Hoses Due to Laceration Hazard



Injuries reported

Hazard: The flexible grease gun hose can develop a hole allowing grease to be ejected

while using the grease gun, posing a laceration hazard.

Remedy:

Consumers should immediately stop using the recalled Makita

Continued on Page 3

-Continued from Page 2

Cordless Grease Guns and Makita Grease Gun Hoses and contact Makita for a free replacement hose.

Units: About 62,927

Consumer Contact:

Website: <http://www.makitatools.com/recall>

E-mail: greasegunrecall@makitausa.com

Phone: [\(800\) 462-5482](tel:(800)462-5482)

TTI Outdoor Power Equipment Recalls RYOBI Pressure Washers Due to Projectile Hazard; Risk of Serious Injury



Injuries reported

Hazard: The pressure washer's capacitor can overheat and burst, causing parts to be forcefully ejected, posing a risk of serious injury from impact to the user or bystanders.

Remedy: Consumers should immediately stop using the recalled pressure washers and visit <https://www.ryobitools.com/recall> to determine if their pressure washer is included in the recall and to receive a

free repair kit, including shipping and installation instructions. The repair kit consists of a replacement capacitor. Proof of purchase (receipt) is not required.

Units: About 764,000 (In addition, about 16,000 were sold in Canada)

Consumer Contact:

Website: <https://www.ryobitools.com/recall>

Phone: [\(800\) 597-9624](tel:(800)597-9624)

Electric Motors for Gable and Roof Mounted Attic Fans Recalled Due to Fire Hazard; Distributed by Air Vent



Hazard: The recalled electric motor's safety cutoff may pose a risk of short circuit and fire hazard while in use.

Remedy: Consumers should immediately stop using the recalled electric motors and contact Air Vent for a refund. Consumers will be asked to fill out the online registration and verification form with photos of

the recalled attic fan motor. Upon confirmation that the consumer has a recalled attic fan motor, the consumer will receive a refund.

Units: About 2.9 million

Consumer Contact:

Website: <https://powermaxmotorrecall.expertinquiry.com>

Phone: [\(877\) 247-4878](tel:(877)247-4878)

Combi Boilers Recalled Due to Burn Hazard; Manufactured by IBC Technologies



Hazard: A combi (or combination) boiler is a type of gas boiler that provides both a home's hot water and central heating. The hot water can exceed the temperature set on the control panel, posing a burn hazard to users.

Remedy: Contact IBC to schedule a free in-home repair by an authorized technician, who will install a mixing

valve, if needed. Consumers can continue to use the recalled boilers for central heating.

Units: About 1,100 (In addition, about 880 were sold in Canada)

Consumer Contact:

Website: <http://www.ibcboiler.com/recalls>

E-mail: sales@ibcboiler.com

Phone: [\(844\) 432-8422](tel:(844)432-8422)

ESR HaloLock Wireless Power Banks Recalled Due to Fire and Burn Hazards; Distributed by Waymeet



Hazard: The lithium-ion battery in the recalled power banks can overheat and ignite, posing fire and burn hazards to consumers.

Remedy: Consumers should immediately stop using the recalled power banks and contact Waymeet for a full refund. Consumers will be asked to send to support@esrtech.com their order number (not required) and a photo of the recalled power bank

showing the model number with the word “Recalled” written on it in permanent marker. Consumers should dispose of the power banks in accordance with local and state hazardous waste disposal regulations.

Note: Do not throw this recalled lithium-ion battery or device in the trash, the general recycling stream (e.g., street-level or curbside recycling bins), or used battery recycling boxes found at various retail and home improvement stores. Recalled lithium-ion batteries must be disposed of differently than other batteries, because they present a greater risk of fire. Your municipal household hazardous waste (HHW) collection center may accept this recalled lithium-ion battery or device for disposal. Before taking your battery or device to a HHW collection center, contact that office ahead of time and ask whether it accepts recalled lithium-ion batteries. If it does not, contact your municipality for further guidance.

Units: About 24,000 (In addition, about 9,900 were sold in Canada)


Consumer Contact:

Website: <https://www.esrtech.com/pages/recall>

E-mail: support@esrtech.com

Phone: [\(888\) 990-0280](tel:(888)990-0280)

Werner Recalls 20' and 24' Multi-Max Pro Multi-Purpose Ladders Due to Fall Hazard



Injuries reported

Hazard: The ladders' locking mechanism can jam and not fully lock into place, posing a fall hazard.

Remedy: Consumers should immediately stop using the recalled ladders and contact Werner to receive a full refund.

Consumers should register at <http://www.wernerco.com/>

[recalls](#) to receive details on how to dispose of the recalled ladder.

Once disposal is complete, Werner will issue a full refund in the form of a check.

Units: About 122,250

Consumer Contact:

Website: <http://>

www.wernerco.com/recalls

E-mail: ladder@realtimeresults.net

Phone: [\(888\) 624-1907](tel:(888)624-1907)

TTI Consumer Power Tools Recalls RIDGID Framing Nailers Due to Laceration Hazard



Hazard: The dual action engagement system on the nailers can malfunction and involuntarily

discharge a nail by pulling the trigger alone, posing a laceration hazard to consumers. The nailer should require both the work piece contact element (nose-piece) to be depressed and the trigger to be pulled at the same time in order to discharge a nail.

Remedy: Consumers should immediately stop using the recalled nailers and

visit powertools.ridgid.com/recall to determine if their nailer is included in the recall and for instructions on how to obtain a free repair. TTI Consumer Power Tools will send a prepaid label to the consumer to return the recalled nailer, the software in the nailer will be updated, and then the nailer will be shipped back to the consumer.

Units: About 64,000 (In addition, about 6,575 were sold in Canada)

Consumer Contact:

Website: <https://powertools.ridgid.com/recall>

Phone: [\(800\) 597-9624](tel:(800)597-9624)

Curtis International Recalls Frigidaire-brand Minifridges Due to Fire and Burn Hazards; More Than \$700,000 Reported in Property Damage



Injuries reported

Hazard: The minifridges' internal electrical components can short circuit and ignite the surrounding plastic housing, posing fire and burn hazards. Curtis International Minifridge Model EFMIS129 - serial numbers between A2001 to A2308 – except for model numbers containing “EFMIS129-B” or “EFMIS129-C”

Remedy: Consumers should immediately stop using the recalled minifridges and follow the instructions to receive a refund

at www.recallrtr.com/minifridge. Consumers should unplug and cut the power cord and write “Recall” using a permanent marker on the front door of the unit. Consumers should dispose of the recalled minifridges in accordance with local and state regulations.

Units: About 634,000

Consumer Contact:

Website: <https://www.recallrtr.com/minifridge>

E-mail: recall@curtiscs.com

Phone: [\(888\) 727-0198](tel:(888)727-0198)

EcoFlow Technology Recalls Delta Max 2000 Power Stations Due to Risk of Serious Burn Injury and Fire Hazard



Hazard: The Power Stations may overheat and ignite, posing a risk of serious burn injury and fire hazard.

Remedy: Consumers should immediately stop using the recalled Power Stations and contact EcoFlow Technology for instructions on

installing a free repair in the form of a firmware update.

Units: About 25,030

Consumer Contact:

Website: <https://www.ecoflow.com/us/blog/ecoflow-delta-max-2000-recall-firmware-update>

E-mail: deltamax2000@ecoflow.com

Phone: [\(833\) 424-4137](tel:(833)424-4137)

iStore Magnetic Wireless Power Banks Recalled Due to Fire and Burn Hazards; Imported by Tomauri



Injuries reported

Hazard: The lithium-ion battery in the recalled power banks can overheat and ignite while charging, posing fire and burn hazards to consumers.

Remedy: Consumers should immediately stop using the recalled wireless portable power bank and go to the firm's website to participate in the recall. Consumers will be asked to submit two photographs via email to recall@istore.co. The first photograph should be the front of the power bank with the word "Recalled" and the date written on it with permanent marker. The second photograph

should include the model number, which is located on the back of the power bank. A purchase receipt will be requested but will not be required to participate in the recall. Consumers should immediately dispose of the power banks in accordance with local and state hazardous waste disposal regulations.

Units: About 8,520 (An additional 6,400 were sold in Canada)

Consumer Contact:

Website: <https://istore.co/pages/battery-recall>

E-mail: recall@istore.co

Phone: [\(800\) 268-4049](tel:(800)268-4049)

Tractor Supply Recalls Traveller Aluminum Loading Ramps Due to Fall Hazard



Injuries reported

Hazard: The ramps cannot withstand the weight of equipment within the limits that are specified on the ramps and can bend or break while in use, posing a fall hazard.

Remedy: Consumers should immediately stop using the recalled ramps. Consumers will be asked to return the ramps to any Tractor Supply store or call the firm for instructions on how

to send a photo of the product with the word "Recalled" using permanent paint to customersolutions@tractorsupply.com for a full refund.

Units: About 18,000

Consumer Contact:

Website: <https://www.tractorsupply.com/tsc/cms/policies-information/customer-solutions/recall-notices>

Phone: [\(877\) 718-6750](tel:(877)718-6750)

Trane Recalls Gas/Electric Packaged Units Due to Risk of Gas Leak, Fire Hazard



Hazard: The fuel gas valve can open unexpectedly, allowing a gas leak and posing a fire hazard.

Remedy: Consumers should immediately stop using the heating mode of the recalled units and contact their dealer who installed the unit to schedule an appointment for a free inspection and repair, by replacing the ignition board of the unit. Consumers with Trane products can locate their nearest dealer at www.trane.com/residential/en/dealer-locator/. Consumers with American Standard products can locate their nearest dealer at www.americanstandardair.com/find-your-dealer/. Consumers can also contact Trane or American Standard directly for support.

Units: About 4,790

Consumer Contact:

Website: <https://www.trane.com/residential/gas-electric-packaged-unit-recall/>

Phone: [\(800\) 889-0129](tel:8008890129)

DEWALT Recalls Grinder Flap Discs Due to Laceration and Injury Hazards



Injuries reported

Hazard: The ceramic cloth abrasive flaps on the disc can detach while in use on a grinder, posing laceration and injury hazards.

Remedy: Consumers should immediately stop using the recalled flap discs and go to the DEWALT

website at <https://www.dewalt.com/support/safety-notices-and-recalls/flap-disc-recall> to participate in the recall. Consumers will be asked to write “Recall” on the disc and upload a photograph to the firm’s website. Consumers will then be asked to certify that they disposed of it in the trash to receive a refund.

Units: About 17,680

Consumer Contact:

Website: <https://www.dewalt.com/support/safety-notices-and-recalls/flap-disc-recall>

E-mail: recall@sbdinc.com

Phone: [\(800\) 990-6421](tel:8009906421)

Harbor Freight Tools Recalls Predator 2000-Watt Power Stations Due to Shock Hazard



Hazard: The wires in the power station’s AC outlet receptacles are reversed when the product is in Emergency Power Supply (“EPS”) mode, posing a shock hazard to consumers operating the power station.

Remedy: Consumers should immediately stop using the recalled power stations and return them to their local Harbor Freight Tools store for a free replacement

unit that will be available at the store. Harbor Freight Tools is contacting all known purchasers directly.

Units: About 6,500

Consumer Contact:

Website: [https://](https://www.harborfreight.com/customer-service-product-support.html#5)

www.harborfreight.com/customer-service-product-support.html#5

E-mail: recall@harborfreight.com

Phone: [\(800\) 444-3353](tel:(800)444-3353)

Positec Recalls Electric Corded Chainsaws and Pole Saws Due to Laceration Hazard



Hazard: The main switch on the recalled chainsaws and pole saws can fail, allowing the

saws to continue to run even after the switch is released, posing a laceration hazard.

Remedy: Consumers should immediately stop using the recalled products and contact Positec for a pre-paid shipping label, and a new box as needed, to return the units free of charge. Positec will provide a free replacement chainsaw or pole saw upon receipt of the recalled product.

Units: About 49,000 (In addition, about 3,000 were sold in Canada)

Consumer Contact:

Website: <https://www.worx.com/chainsaw-recall>

E-mail: chainsawrecall@positecgroup.com

Phone: [\(888\) 997-8871](tel:(888)997-8871)

DR Power Recalls Lithium-Ion Battery Packs Due to Fire and Burn Hazards



Hazard: The recalled battery packs can short-circuit and ignite, posing fire and burn hazards to consumers.

Remedy: Consumers should immediately stop using the recalled battery packs and contact DR Power for a pro-rated refund, based on the battery's age. Consumers will need to show proof of the battery pack's destruction by uploading two photographs in accordance with the destruction instructions (provided on the firm's recall

website), and filling out the recall form online at <https://www.drpower.com/5AHB-recall>. If consumers choose to dispose of the recalled battery pack's lithium-ion battery, it should be done in accordance with local and state regulations.

Units: About 13,200

Consumer Contact:

Website: <https://drpower.com/recalls>

E-mail: recall@drpower.com

Phone: [\(800\) 454-8643](tel:(800)454-8643)

AstroAI Recalls Minifridges Due to Fire and Burn Hazards; Two Fires Resulted in More Than \$360,000 in Reported Property Damages



Hazard: The recalled minifridges' electrical switch can short circuit, posing fire and burn hazards.

Remedy: Consumers should immediately stop using the recalled minifridges and contact AstroAI for a free replacement minifridge. To receive a replacement minifridge, consumers should send a photo of the recalled minifridge, showing the model number and serial number, with "Recalled" written on the minifridge in permanent marker to AstroAI by email

at recall@astroai.com or through the online portal at <https://www.astroai.com/product-recall>.

Consumers should dispose of the recalled minifridges in accordance with state and local waste disposal procedures.

Units: About 249,100

Consumer Contact:

Website: <https://www.astroai.com/product-recall>

E-mail: recall@astroai.com

Phone: [\(877\) 278-7624](tel:(877)278-7624)

TTI Outdoor Power Equipment Recalls RYOBI 40-Volt 24-Inch Cordless Hedge Trimmers Due to Laceration Hazard



Injuries reported

Hazard: The hedge trimmer blade can unexpectedly activate after pressing just the safety or trigger control individually rather than engaging the safety and trigger controls simultaneously, posing a laceration hazard.

Remedy: Consumers should immediately stop using the recalled RYOBI 40V 24-Inch Cordless Hedge Trimmers and visit <https://www.ryobitools.com/recall> to determine if their trimmer is

included in the recall. The recalled trimmer must be returned to TTI Outdoor Power Equipment (TTIOPE), in order to receive a free replacement trimmer (pre-paid label will be provided). Proof of purchase (receipt) is not required. TTIOPE is contacting all known purchasers.

Units: About 113,000 (In addition, about 15,000 were sold in Canada)

Consumer Contact:

Website: [https://](https://www.ryobitools.com/recall)

www.ryobitools.com/recall

Phone: [\(800\) 597-9624](tel:8005979624)

More than One Million Anker Power Banks Recalled Due to Fire and Burn Hazards; Manufactured by Anker Innovations



Injuries reported

Hazard: The lithium-ion battery in the power bank can overheat, posing fire and burn hazards to consumers.

Remedy: Consumers should immediately stop using the recalled power banks and contact Anker Innovations for instructions on receiving a free replacement power bank. Visit <https://www.anker.com/product-recalls> to register for the recall. To receive a replacement, consumers will be required to submit a photo of their recalled power bank showing the model number, serial number, their

name, the date of the photograph, and the word “recalled” written on the power bank in permanent marker. A purchase receipt will be requested but will not be required to participate in the recall. Consumers will also be required to confirm disposal of the power bank in accordance with applicable laws and regulations before receiving a replacement.

Units: About 1,158,000

Consumer Contact:

Website: [https://](https://support.anker.com/s/emailcontactus)

support.anker.com/s/emailcontactus

E-mail: support@anker.com

Phone: [\(800\) 988-7973](tel:8009887973)

NTI Brand Boilers Recalled Due to Fire and Carbon Monoxide (CO) Poisoning Hazards and Risk of Serious Injury or Death; Made by NTI Boilers



Hazard: The boiler door can fail to seal properly, due to incorrect burner door studs, allowing flames and gases to escape, posing fire and carbon monoxide (CO) poisoning hazards that can result in death or serious injury.

Remedy: Consumers should immediately stop using the recalled boilers and contact NTI Boilers to arrange to have a certified technician install the repair at no

cost to the consumer. Consumers who must continue using the boiler while awaiting repair should have working smoke and carbon monoxide alarms in their homes.

Units: About 323 (In addition, 459 were sold in Canada)

Consumer Contact:

Website: <http://www.ntiboilers.com/trx-safety-recall>

E-mail: recall@ntiboilers.com

HTP Brand Boilers Recalled Due to Fire and Carbon Monoxide (CO) Poisoning Hazards and Risk of Serious Injury or Death; Made by NTI Boilers



Hazard: The boiler door can fail to seal properly, due to incorrect burner door studs, allowing flames and gases to escape, posing fire and carbon monoxide (CO) poisoning hazards that can result in death or serious injury.

Remedy: Consumers should immediately stop using the recalled boilers and contact HTP to arrange to have a certified technician install the

repair at no cost to the consumer. Consumers who must continue using the boiler while awaiting repair should have working smoke and carbon monoxide alarms in their homes.

Units: About 96 (In addition, 9 were sold in Canada)

Consumer Contact:

Website: <https://htproducts.com/safety-notice.html>

E-mail: recall@htproducts.com

Phone: [\(800\) 323-9651](tel:(800)323-9651)

DR Power Equipment Recalls Battery-Powered Chainsaws Due to Fire and Burn Hazards



Hazard: The motor controller of the recalled chainsaw can overheat during operation of the unit, posing fire and burn hazards.

Remedy: Consumers should immediately stop using the recalled chainsaws and contact DR Power for a refund. Consumers will receive a pro-rated refund for the chainsaw tool based on the chainsaw's age. Consumers will need to show proof of the chainsaw's destruction by uploading a photograph in accordance with the destruction instructions and filling out the recall

form online. For instructions on destroying the chainsaw, visit <https://www.drpower.com/BPC-recall>. If consumers choose to dispose of the recalled chainsaw's lithium-ion battery, consumers should recycle the lithium-ion batteries in accordance with local and state regulations.

Units: About 7,180 (In addition, about 21 were sold in Canada)

Consumer Contact:

Website: <http://drpower.com/recalls>
 E-mail: recalls@DRPower.com
 Phone: [\(800\) 940-6923](tel:(800)940-6923)

Lutron Recalls Power Interfaces for LED Tape Lights Due to Shock Hazard



Hazard: The power interface can fail during a significant power surge (e.g., lightning strike), posing a shock hazard to consumers if they touch the LED tape lights.

Remedy: Consumers should immediately stop using the recalled power interfaces and any connected lighting and turn off the power at the circuit breaker. Consumers should contact Lutron for instructions on how to receive their free replacement power

interface and how it will be installed at no charge. Consumers should go to <https://residential.lutron.com/us/en/safety/safety-recall> to determine if their unit is included in this recall and, if so, to register to receive installation of the replacement power interface. If a unit is included, Lutron will provide the free replacement power interface and a pre-paid mailing label that the consumer can use to return the unit to Lutron.

Units: About 1,944

Consumer Contact:

Website: <https://residential.lutron.com/us/en/safety/safety-recall>
 E-mail: productrecall@lutron.com
 Phone: [\(800\) 239-0495](tel:(800)239-0495)

Rinnai America Recalls Boilers Due to Carbon Monoxide (CO) Poisoning Hazard



Hazard: The boiler door can fail to seal properly due to incorrect screws, allowing carbon monoxide (CO) gases to escape, posing a carbon monoxide poisoning hazard.

Remedy: Consumers should immediately stop using the recalled boilers and contact

Rinnai to arrange to have a certified technician install the repair at no cost to the consumer.

Consumers who must continue using the boiler while awaiting repair should have working carbon monoxide alarms on each level of their homes and outside sleeping areas.

Units: About 2,030 (In addition, 249 were sold in Canada)

Consumer Contact:

Website: <https://www.rinnai.us/support/recalls>

E-mail: recall@rinnai.us

Phone: [\(800\) 621-9419](tel:(800)621-9419)

iWALK Magnetic Wireless Power Banks Recalled Due to Fire and Burn Hazards; Manufactured by U2O Global



Injuries reported

Hazard: The lithium-ion batteries in the recalled power banks can overheat and ignite, posing a risk of serious injury or death from fire and burn hazards to consumers.

Remedy: Consumers should immediately stop using the recalled power banks and contact U2O Global for a full refund. To receive a refund, consumers should send a photo of the recalled power bank, showing the model

number and the serial number, with “Recalled” written on the power bank in permanent marker to U2O Global by email at service@iwalk.net. Consumers should dispose of the recalled power banks in accordance with local hazardous waste disposal procedures.

Units: About 27,500

Consumer Contact:

Website: <https://www.iwalk.net/recall.html>

E-mail: service@iwalk.net

Phone: [\(888\) 279-0111](tel:(888)279-0111)

Got an important message for your fellow NABO members? Have an announcement that you'd like to share? Send your submissions for the NABO NOW! newsletter to allison.toensing@tuvsud.com



www.nabomembers.com

NABO GRANT PROGRAM

THE PROGRAM

The National Association of Boiler Owners and Operators (“NABO”) has established a Grant program to provide for and encourage eligible individuals to continue their education to pass the National Board Examination for boiler and pressure vessel inspectors and to become a National Board Commissioned Inspector.

This Grant program is administered by NABO. All awards are granted without regard to race, color, creed, religion, sexual orientation, gender, disability or national origin.

ELIGIBILITY

Applicants to the NABO Grant Program must be either:

- Children of individuals employed by or affiliated with ARISE Boiler Inspection and Insurance Company Risk Retention Group policyholder companies (“ABIIC”);
- Individuals who want to become commissioned boiler inspectors;
- Veterans of the United States Military Services; or
- Individuals with HVAC or Code or Non-Code boiler and pressure vessel manufacturing shop experience as a Welder or Quality Control.
- Must be a citizen of the United States.

ELIGIBLE EDUCATIONAL INSTITUTIONS

An Eligible Educational Institution is any accredited school that has a curriculum to prepare students to pass the National Board Examination to become a National Board Commissioned Inspector. See current National Board requirements here <http://www.nationalboard.org/Index.aspx?pageID=390&ID=483>

AWARDS

Applications will be reviewed against the program criteria by a selection process determined by NABO. Grant recipients will be selected on a competitive basis. If selected as a Grant Recipient, the student will receive an award in an amount of \$10,000 for tuition, books and related fees. Up to two awards will be granted each year. Applicants can reapply for additional awards each year while continuing their education.

APPLICATION

Interested individuals must complete the Application and submit it to:

NABO Grant Program

c/o ARISE Boiler Inspection & Insurance Co. RRG 7000 S.
Edgerton Road, Suite 100
Brecksville, OH 44141
Email: arise-NABO@tuv sud.com

Continued on Page 16

-Continued from Page 15

Applicants are responsible for gathering and submitting all necessary information. Applications are evaluated on the information supplied; therefore, answer all questions as completely as possible. Incomplete applications will not be evaluated. All information received is considered confidential and is reviewed only by the NABO Grant Program Selection Committee.

SELECTION OF GRANT RECIPIENTS

Grant Recipients are selected on the basis of academic record, demonstrated leadership and participation in school and community activities, honors, work experience, statement of goals and aspirations, and a personal interview, if elected by the NABO Grant Program Selection Committee. Financial need is not considered.

Selection of Grant Recipients is made by the NABO Grant Program Selection Committee. All Applicants agree to accept the decision as final.

Grant Recipients will be notified as soon as possible after receipt of the completed application. Not all applicants to the program will be selected as Grant Recipients. Students may reapply to the program each year they meet eligibility requirements.

PAYMENT OF GRANTS

All awards will be paid directly to the Eligible Educational Institution. Grant Recipients will be responsible for all income taxes due on any awards.

OBLIGATIONS

Grant Recipients must keep at least a "C" average in all courses in order to keep the award. If the recipient's grades fall below a "C" average in his or her courses, the Grant Recipient shall be required to repay the award to NABO. Grant Recipients must submit a transcript of courses taken and grades received to the NABO Grant Program Selection Committee at the end of each grading period.

AMENDMENTS AND TERMINATION OF NABO GRANT PROGRAM

NABO reserves the right to review the conditions and procedures of the NABO Grant Program and to make any changes at any time, including termination of the NABO Grant Program.

ADDITIONAL INFORMATION

Questions regarding the NABO Grant Program should be addressed to: NABO

NABO Grant Program

c/o ARISE Boiler Inspection & Insurance Co. RRG
7000 S. Edgerton Road, Suite 100
Brecksville, OH 44141
Email: arise-NABO@tuvsud.com

Continued on Page 17

-Continued from Page 16

NABO Grant Program Application

I, _____ have read and understand the conditions of the NABO grant Program. I affirm that I plan to pursue a career in boiler and pressure vessel inspection and to sit for the National Board Examination to become a National Board Commissioned Inspector. I give permission to officials of my educational institution to release transcripts of my academic record and other information requested for consideration in the NABO Grant Program. I understand that this application will be available only to qualified people who are pursuing a career in boiler and pressure vessel inspection. I affirm the information contained herein is true and accurate to the best of my knowledge and belief.

Date _____ Signature _____

Legal name in full _____
(Print/Type) Last Name First Name M.I.

Permanent residence _____
Number, Street, and Apartment Number

City State ZIP

Your address at school _____
(if different) Number, Street, and Apartment Number

City State ZIP

Home telephone (_____) _____

School telephone (_____) _____
(if different)

E-mail address _____

(Check one) I am a U.S. citizen U.S. national Resident alien expecting citizenship by the date of award

Date of birth _____
Month/Day/Year

Name of Educational Institution _____

Current cumulative GPA _____ on a scale of _____

Your undergraduate major(s) _____

Number of college credits earned to date _____ Total number of credits required for graduation _____

Expected date to receive baccalaureate degree _____ Degree you will receive _____

Graduate degree(s) sought _____ Concentration(s) _____

-Continued from Page 17

Name _____

1. List the secondary school from which you graduated, and all higher education institutions attended.

School	Location	Dates Attended
--------	----------	----------------

2. List awards, scholarships, or special recognitions you have received.

3. List college and high school activities

4. List work experience

